English Cymraeg


Energy performance certificate (EPC)

| 173 Crawfordsburn Road BANGOR BT19 1BT | Energy rating | Valid until: | 12 June 2034 |
|--|---------------|------------------------|--------------------------|
| | | Certificate number: | 0820-9568-0126-2100-0433 |
| Property type Detached house | | | |
| Total floor area 340 square metres | | etres | |

Energy rating and score

This property's energy rating is E. It has the potential to be D.

See how to improve this property's energy efficiency.



The graph shows this property's current and potential energy rating.

Properties get a rating from A (best) to G (worst) and a score. The better the rating and score, the lower your energy bills are likely to be.

For properties in Northern Ireland:

- the average energy rating is D
- the average energy score is 60

Breakdown of property's energy performance

Features in this property

Features get a rating from very good to very poor, based on how energy efficient they are. Ratings are not based on how well features work or their condition.

Assumed ratings are based on the property's age and type. They are used for features the assessor could not inspect.

6/13/24, 2:40 PM

Energy performance certificate (EPC) – Find an energy certificate – GOV.UK

| Feature | Description | Rating |
|----------------------|---|-----------|
| Wall | Granite or whinstone, as built, no insulation (assumed) | Very poor |
| Wall | Cavity wall, as built, insulated (assumed) | Good |
| Roof | Pitched, 400+ mm loft insulation | Very good |
| Roof | Roof room(s), insulated | Good |
| Roof | Pitched, insulated (assumed) | Good |
| Window | Mostly double glazing | Good |
| Main heating | Boiler and radiators, oil | Average |
| Main heating control | Programmer, no room thermostat | Very poor |
| Hot water | From main system, no cylinder thermostat | Poor |
| Lighting | Low energy lighting in 74% of fixed outlets | Very good |
| Floor | Solid, no insulation (assumed) | N/A |
| Floor | Solid, insulated (assumed) | N/A |
| Secondary heating | Room heaters, wood logs | N/A |

Low and zero carbon energy sources

Low and zero carbon energy sources release very little or no CO2. Installing these sources may help reduce energy bills as well as cutting carbon emissions. The following low or zero carbon energy sources are installed in this property:

· Biomass secondary heating

Primary energy use

The primary energy use for this property per year is 228 kilowatt hours per square metre (kWh/m2).

About primary energy use

Additional information

Additional information about this property:

Stone walls present, not insulated

How this affects your energy bills

An average household would need to spend £5,366 per year on heating, hot water and lighting in this property. These costs usually make up the majority of your energy bills.

You could save £1,237 per year if you complete the suggested steps for improving this property's energy rating.

This is **based on average costs in 2024** when this EPC was created. People living at the property may use different amounts of energy for heating, hot water and lighting.

Impact on the environment

This property's environmental impact rating is E. It has the potential to be E.

Properties get a rating from A (best) to G (worst) on how much carbon dioxide (CO2) they produce each year.

Carbon emissions

An average household produces 6 tonnes of CO2 This property produces 18.5 tonnes of CO2

https://find-energy-certificate.service.gov.uk/energy-certificate/0820-9568-0126-2100-0433

This property's potential production

You could improve this property's CO2 emissions by making the suggested changes. This will help to protect the environment.

These ratings are based on assumptions about average occupancy and energy use. People living at the property may use different amounts of energy.

Changes you could make

Do I need to follow these steps in order?

Step 1: Heating controls (room thermostat and TRVs)

| Typical installation cost | £350 - £450 |
|--|-------------|
| Typical yearly saving | £630 |
| Potential rating after completing step 1 | 50 E |

Step 2: Room-in-roof insulation

| Typical installation cost | £1,500 - £2,700 |
|---|-----------------|
| Typical yearly saving | £115 |
| Potential rating after completing steps 1 and 2 | 52 E |

Step 3: Replace boiler with new condensing boiler

| Typical installation cost | £2,200 - £3,000 |
|--|-----------------|
| Typical yearly saving | £491 |
| Potential rating after completing steps 1 to 3 | 57 D |

Step 4: Solar water heating

| Typical installation cost | £4,000 - £6,000 |
|--|-----------------|
| Typical yearly saving | £83 |
| Potential rating after completing steps 1 to 4 | 58 D |

Step 5: Internal or external wall insulation

| Typical installation cost | £4,000 - £14,000 |
|--|------------------|
| Typical yearly saving | £1,036 |
| Potential rating after completing steps 1 to 5 | 70 C |

Step 6: Solar photovoltaic panels, 2.5 kWp

| Typical installation cost | £3,500 - £5,500 |
|---------------------------|-----------------|
| Typical yearly saving | £520 |

Potential rating after completing steps 1 to 6

Help paying for energy improvements

You might be able to get a grant from the Boiler Upgrade Scheme (https://www.gov.uk/apply-boiler-upgrade-scheme). This will help you buy a more efficient, low carbon heating system for this property.

Who to contact about this certificate

Contacting the assessor

If you're unhappy about your property's energy assessment or certificate, you can complain to the assessor who created it.

| Assessor's name | Chris McLean |
|-----------------|----------------------------|
| Telephone | 07751695309 |
| Email | chris.mclean54@yahoo.co.uk |

Contacting the accreditation scheme

If you're still unhappy after contacting the assessor, you should contact the assessor's accreditation scheme.

| Accreditation scheme | Quidos Limited |
|----------------------|-------------------|
| Assessor's ID | QUID209992 |
| Telephone | 01225 667 570 |
| Email | info@quidos.co.uk |

About this assessment

| Assessor's declaration | No related party |
|------------------------|------------------|
| Date of assessment | 12 June 2024 |
| Date of certificate | 13 June 2024 |
| Type of assessment | ► <u>RdSAP</u> |

Other certificates for this property

If you are aware of previous certificates for this property and they are not listed here, please contact us at <u>dluhc.digital-services@levellingup.gov.uk</u> or call our helpdesk on 020 3829 0748 (Monday to Friday, 9am to 5pm).

There are no related certificates for this property.

<u>Help (/help)</u> <u>Accessibility (/accessibility-statement)</u> <u>Cookies (/cookies)</u> Give feedback (https://forms.office.com/e/hUnC3Xq1T4) Service performance (/service-performance)

OGL

All content is available under the <u>Open Government Licence v3.0 (https://www.nationalarchives.gov.uk/doc/open-government-licence/version/3/)</u>, except where otherwise stated



ht (https://www.nationalarchives.gov.uk/information-management/re-using-public-sector-information/uk-government-licensing-framewor